

Base Line Item Detail					D'annunzio & Sons, Inc.		Joseph M. Sanzari, Inc.		Gardner M. Bishop, Inc.		Railroad Construction Co., Inc.	
Item No.	Unit Code	QTY	UNIT	DESCRIPTION	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT
0001	1D01LAY	1	L.S.	Construction Layout	\$10,020.00	\$10,020.00	\$20,600.00	\$20,600.00	\$10,000.00	\$10,000.00	\$25,000.00	\$25,000.00
0002	1D10MOB	1	L.S.	Mobilization	\$600,000.00	\$600,000.00	\$600,000.00	\$600,000.00	\$10,000.00	\$10,000.00	\$630,000.00	\$630,000.00
0003	1G01SCH	1	L.S.	Progress Schedule	\$20,000.00	\$20,000.00	\$8,190.00	\$8,190.00	\$1,000.00	\$1,000.00	\$20,000.00	\$20,000.00
0004	1HFP0B	1	L.S.	Fuel Price Adjustment (NO-BID)	\$4,000.00	\$4,000.00	\$4,000.00	\$4,000.00	\$4,000.00	\$4,000.00	\$4,000.00	\$4,000.00
0005	2BETU0B	1	L.S.	Environmental Testing for Unsuitable and Excess Materials (NO-BID)	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00
0006	2J01DES	1	L.S.	Demolition of Existing Structures	\$200,000.00	\$200,000.00	\$8,400.00	\$8,400.00	\$80,000.00	\$80,000.00	\$50,000.00	\$50,000.00
0007	3B01PJA	34020	L.F.	Polymerized Joint Adhesive	\$1.50	\$51,030.00	\$1.50	\$51,030.00	\$2.00	\$68,040.00	\$1.30	\$44,226.00
0008	3B25SUP	4800	Ton	Superpave Hot Mix Asphalt 12.5H 76 Surface Course	\$210.00	\$1,008,000.00	\$199.00	\$955,200.00	\$250.00	\$1,200,000.00	\$160.00	\$768,000.00
0009	3B33SUP	1760	Ton	Superpave Hot Mix Asphalt 19H 64 Intermediate Course	\$200.00	\$352,000.00	\$153.00	\$269,280.00	\$250.00	\$440,000.00	\$150.00	\$264,000.00
0010	3B43SUP	575	Ton	Superpave Hot Mix Asphalt with Rosphalt	\$600.00	\$345,000.00	\$553.00	\$317,975.00	\$550.00	\$316,250.00	\$550.00	\$316,250.00
0011	3B26TAC	11000	GAL	Tack Coat	\$9.00	\$99,000.00	\$9.00	\$99,000.00	\$7.50	\$82,500.00	\$9.00	\$99,000.00
0012	3B30CLS	6000	L.F.	Cleaning Inside Shoulders	\$1.00	\$6,000.00	\$0.80	\$4,800.00	\$1.00	\$6,000.00	\$1.00	\$6,000.00
0013	3B31CLS	41000	L.F.	Cleaning Outside Shoulders	\$1.00	\$41,000.00	\$0.50	\$20,500.00	\$1.00	\$41,000.00	\$1.00	\$41,000.00
0014	3B30HMA	16	Ton	Temporary Surfacing	\$600.00	\$9,600.00	\$300.00	\$4,800.00	\$700.00	\$11,200.00	\$3,000.00	\$48,000.00
0015	3B41SCS	3000	L.F.	Sealing Cracks in Bituminous Surface	\$2.00	\$6,000.00	\$5.00	\$15,000.00	\$3.00	\$9,000.00	\$3.00	\$9,000.00
0016	3B42ASB	20300	S.Y.	Membrane Waterproofing	\$20.00	\$406,000.00	\$21.00	\$426,300.00	\$12.00	\$243,600.00	\$30.00	\$609,000.00
0017	3B45HPP	20	Ton	High Performance Cold Patch	\$300.00	\$6,000.00	\$300.00	\$6,000.00	\$200.00	\$4,000.00	\$200.00	\$4,000.00
0018	3B52CSM	325	L.F.	Crack Spanning Membrane	\$15.00	\$4,875.00	\$10.50	\$3,412.50	\$20.00	\$6,500.00	\$25.00	\$8,125.00
0019	3BAPA0B	1	L.S.	Asphalt Price Adjustment (NO-BID)	\$5,000.00	\$5,000.00	\$5,000.00	\$5,000.00	\$5,000.00	\$5,000.00	\$5,000.00	\$5,000.00
0020	3D05ASR	50	S.F.	Approach Slab Spall Repair, Type 1	\$50.00	\$2,500.00	\$80.00	\$4,000.00	\$60.00	\$3,000.00	\$140.00	\$7,000.00
0021	3D06ASR	50	S.F.	Approach Slab Spall Repair, Type 2	\$75.00	\$3,750.00	\$129.00	\$6,450.00	\$90.00	\$4,500.00	\$160.00	\$8,000.00
0022	3E14PMR	10400	S.Y.	Pavement Removal, 5" Depth	\$25.00	\$260,000.00	\$20.00	\$208,000.00	\$35.00	\$364,000.00	\$40.00	\$416,000.00
0023	3E20PMR	12200	S.Y.	Pavement Removal, Variable Depth	\$25.00	\$305,000.00	\$18.50	\$225,700.00	\$35.00	\$427,000.00	\$20.00	\$244,000.00
0024	3E40PMR	25.00	S.Y.	Surface Milling	\$25.00	\$625.00	\$16.00	\$400.00	\$60.00	\$1,500.00	\$20.00	\$500.00
0025	3E55PMR	45.00	L.F.	Remove Existing Rumble Strip	\$50.00	\$2,250.00	\$50.00	\$2,250.00	\$50.00	\$2,250.00	\$100.00	\$4,500.00
0026	3F01MRS	130	L.F.	Milled Rumble Strip	\$15.00	\$1,950.00	\$30.00	\$3,900.00	\$50.00	\$6,500.00	\$70.00	\$9,100.00
0027	3L01SSJ	275.00	L.F.	Sawing and Sealing Joints in Asphalt Concrete Overlay	\$25.00	\$6,875.00	\$6.00	\$1,650.00	\$10.00	\$2,750.00	\$50.00	\$13,750.00
0028	4A11RFS	139,500.00	LB	Reinforcement Steel, Epoxy Coated	\$2.00	\$279,000.00	\$2.00	\$279,000.00	\$1.00	\$139,500.00	\$2.20	\$306,900.00
0029	4A12RBC	130	Each	Reinforcement Bar Coupler	\$50.00	\$6,500.00	\$40.00	\$5,200.00	\$30.00	\$3,900.00	\$80.00	\$10,400.00
0030	4A00025	55	L.F.	Neoprene Strip Seal	\$50.00	\$2,750.00	\$20.00	\$1,100.00	\$120.00	\$6,600.00	\$100.00	\$5,500.00
0031	4A15DGR	130	Each	Drill and Grout Reinforcement Bars	\$25.00	\$3,250.00	\$35.00	\$4,550.00	\$100.00	\$13,000.00	\$60.00	\$7,800.00
0032	4K09PES	860	S.F.	Painting Existing Steelwork	\$45.00	\$38,700.00	\$29.30	\$25,198.00	\$30.00	\$25,800.00	\$20.00	\$17,200.00
0033	4L03BDI	2	Each	Raise Bridge Drop Inlet	\$2,500.00	\$5,000.00	\$1,300.00	\$2,600.00	\$1,500.00	\$3,000.00	\$4,000.00	\$8,000.00
0034	4L04BDI	60	Each	Repair Bridge Drop Inlet	\$1,500.00	\$90,000.00	\$1,130.00	\$67,800.00	\$2,000.00	\$120,000.00	\$4,000.00	\$240,000.00
0035	4L05CBD	360	L.F.	Clean Bridge Drainage System	\$60.00	\$21,600.00	\$15.00	\$5,400.00	\$25.00	\$9,000.00	\$35.00	\$12,600.00
0036	4L08WIG	170	Each	Weld Existing Inlet Grate	\$750.00	\$127,500.00	\$450.00	\$76,500.00	\$500.00	\$85,000.00	\$700.00	\$119,000.00
0037	4Q02BDR	225	S.Y.	Concrete Deck Replacement	\$550.00	\$123,750.00	\$800.00	\$180,000.00	\$1,295.00	\$291,375.00	\$1,200.00	\$270,000.00
0038	4Q03BDR	1225	S.Y.	Concrete Deck Replacement with Catches	\$800.00	\$980,000.00	\$1,120.00	\$1,372,000.00	\$1,300.00	\$1,592,500.00	\$1,600.00	\$1,960,000.00
0039	4Q06BDR	60	L.F.	Pavement Riser Repair	\$150.00	\$9,000.00	\$155.00	\$9,300.00	\$140.00	\$8,400.00	\$220.00	\$13,200.00
0040	4Q08BDR	19600	S.Y.	Removal of Existing Surfacing	\$32.00	\$627,200.00	\$40.00	\$784,000.00	\$60.00	\$1,176,000.00	\$57.00	\$1,117,200.00
0041	4Q09BDR	150	S.F.	Removal and Replacement of Existing Surfacing	\$30.00	\$4,500.00	\$45.00	\$6,750.00	\$40.00	\$6,000.00	\$57.00	\$8,550.00
0042	4Q18SJS	2650	L.F.	Silicone Joint Seal	\$55.00	\$145,750.00	\$6.30	\$16,695.00	\$25.00	\$66,250.00	\$10.00	\$26,500.00
0043	4Q20H01	10	L.F.	Headblock Repair, Type 1	\$200.00	\$2,000.00	\$63.00	\$630.00	\$200.00	\$2,000.00	\$400.00	\$4,000.00
0044	4Q20H02	130	L.F.	Headblock Repair, Type 2	\$250.00	\$32,500.00	\$194.25	\$25,252.50	\$350.00	\$45,500.00	\$400.00	\$52,000.00
0045	4Q20H03	10	L.F.	Headblock Repair, Type 3	\$300.00	\$3,000.00	\$195.00	\$1,950.00	\$400.00	\$4,000.00	\$400.00	\$4,000.00
0046	4Q22BDR	100	S.Y.	Removal of SIP Metal Forms	\$80.00	\$8,000.00	\$14.00	\$1,400.00	\$150.00	\$15,000.00	\$120.00	\$12,000.00
0047	4Q24BDR	19600	L.F.	Reinforcement Steel, Field Anti - Corrosion Coating	\$5.00	\$98,000.00	\$0.50	\$9,800.00	\$5.00	\$98,000.00	\$9.00	\$176,400.00
0048	4QFAE0B	1	C.P.	Force Account for Emergency and Routine Bridge Repairs (NO-BID)	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00
0049	4QFA2E0B	1	C.P.	Force Account for Emergency and Routine Bridge Repairs on NBHCE (NO-BID)	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00	\$300,000.00
0050	4Q30S01	32000	S.F.	Spall Repair, Type 1	\$32.00	\$1,024,000.00	\$45.00	\$1,440,000.00	\$20.00	\$640,000.00	\$60.00	\$1,920,000.00
0051	4Q30S02	150.00	S.F.	Spall Repair, Type 2	\$40.00	\$6,000.00	\$90.00	\$13,500.00	\$120.00	\$18,000.00	\$110.00	\$16,500.00
0052	4Q30S04	100.00	S.F.	Spall Repair, Type 4	\$150.00	\$15,000.00	\$139.00	\$13,900.00	\$300.00	\$30,000.00	\$160.00	\$16,000.00

Base Line Item Detail					D'annunzio & Sons, Inc.		Joseph M. Sanzari, Inc.		Gardner M. Bishop, Inc.		Railroad Construction Co., Inc.	
Item No.	Unit Code	QTY	UNIT	DESCRIPTION	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT
0053	4Q30S05	200	S.F.	Spall Repair, Type 5	\$30.00	\$6,000.00	\$136.00	\$27,200.00	\$130.00	\$26,000.00	\$140.00	\$28,000.00
0054	4Q30S5A	200	S.F.	Spall Repair, Type 5A	\$30.00	\$6,000.00	\$124.00	\$24,800.00	\$140.00	\$28,000.00	\$140.00	\$28,000.00
0055	4Q30S5B	200.00	S.F.	Spall Repair, Type 5B	\$50.00	\$10,000.00	\$124.00	\$24,800.00	\$150.00	\$30,000.00	\$150.00	\$30,000.00
0056	4Q30S06	250	S.F.	Spall Repair, Type 6	\$100.00	\$25,000.00	\$185.00	\$46,250.00	\$150.00	\$37,500.00	\$190.00	\$47,500.00
0057	4Q30S6A	250	S.F.	Spall Repair, type 6A	\$100.00	\$25,000.00	\$168.00	\$42,000.00	\$180.00	\$45,000.00	\$200.00	\$50,000.00
0058	4Q30SUD	805	S.F.	Repair Underdeck Spalls (Clean and Coat)	\$100.00	\$80,500.00	\$25.00	\$20,125.00	\$200.00	\$161,000.00	\$100.00	\$80,500.00
0059	4Q50J1A	2000	L.F.	Joint Reconstruction, Type 1A	\$150.00	\$300,000.00	\$210.00	\$420,000.00	\$150.00	\$300,000.00	\$160.00	\$320,000.00
0060	4Q50J1P	250	L.F.	Joint Reconstruction, Type 1P	\$200.00	\$50,000.00	\$325.00	\$81,250.00	\$400.00	\$100,000.00	\$250.00	\$62,500.00
0061	4Q50JFJ	290	L.F.	Joint Reconstruction, Type FJ	\$100.00	\$29,000.00	\$200.00	\$58,000.00	\$80.00	\$23,200.00	\$90.00	\$26,100.00
0062	4Q51J1P	10	L.F.	Joint Replacement, Type 1P	\$200.00	\$2,000.00	\$300.00	\$3,000.00	\$400.00	\$4,000.00	\$250.00	\$2,500.00
0063	4Q60J25	160	L.F.	Joint Seal Replacement, Type 25W	\$150.00	\$24,000.00	\$144.00	\$23,040.00	\$100.00	\$16,000.00	\$60.00	\$9,600.00
0064	4Q60J30	500.00	L.F.	Joint Seal Replacement, Type 30W	\$160.00	\$80,000.00	\$149.00	\$74,500.00	\$110.00	\$55,000.00	\$70.00	\$35,000.00
0065	4Q60J40	290	L.F.	Joint Seal Replacement, Type 40W	\$160.00	\$46,400.00	\$152.00	\$44,080.00	\$110.00	\$31,900.00	\$72.00	\$20,880.00
0066	4Q60J50	130.00	L.F.	Joint Seal Replacement, Type 50W	\$170.00	\$22,100.00	\$156.00	\$20,280.00	\$120.00	\$15,600.00	\$80.00	\$10,400.00
0067	4Q60J65	80	L.F.	Joint Seal Replacement, Type 65W	\$180.00	\$14,400.00	\$160.00	\$12,800.00	\$150.00	\$12,000.00	\$95.00	\$7,600.00
0068	4Q4J100	20	L.F.	Joint Seal Replacement, Type IV-100	\$150.00	\$3,000.00	\$17.00	\$340.00	\$85.00	\$1,700.00	\$230.00	\$4,600.00
0069	4Q4J150	20	L.F.	Joint Seal Replacement, Type IV-150	\$150.00	\$3,000.00	\$19.00	\$380.00	\$85.00	\$1,700.00	\$200.00	\$4,000.00
0070	4Q4J200	60	L.F.	Joint Seal Replacement, Type IV-200	\$150.00	\$9,000.00	\$24.00	\$1,440.00	\$90.00	\$5,400.00	\$210.00	\$12,600.00
0071	4Q4J250	10.00	L.F.	Joint Seal Replacement, Type IV-250	\$150.00	\$1,500.00	\$33.00	\$330.00	\$95.00	\$950.00	\$250.00	\$2,500.00
0072	N4Q0001	1	L.S.	Concrete Repair Material	\$15,000.00	\$15,000.00	\$8,000.00	\$8,000.00	\$15,000.00	\$15,000.00	\$35,000.00	\$35,000.00
0073	N4Q0002	200	S.F.	Furnishing, Installation and Removal of Temporary Shielding	\$25.00	\$5,000.00	\$14.70	\$2,940.00	\$50.00	\$10,000.00	\$180.00	\$36,000.00
0074	N4Q0012	186	L.F.	Furnishing, Installation and Removal of Temporary Shielding	\$250.00	\$46,500.00	\$300.00	\$55,800.00	\$300.00	\$55,800.00	\$320.00	\$59,520.00
0075	4Q80RLC	4970	S.Y.	Removal of Latex Modified Concrete Overlay, Variable Thickness	\$30.00	\$149,100.00	\$25.00	\$124,250.00	\$60.00	\$298,200.00	\$30.00	\$149,100.00
0076	4N05BRL	290.00	L.F.	Bridge Railing	\$400.00	\$116,000.00	\$213.00	\$61,770.00	\$275.00	\$79,750.00	\$160.00	\$46,400.00
0077	4N12BRL	75.00	L.F.	Reset Bridge Railing	\$80.00	\$6,000.00	\$114.00	\$8,550.00	\$150.00	\$11,250.00	\$40.00	\$3,000.00
0078	4R01BSR	6100	S.F.	Sidewalk, Parapet and Curb Surface Repairs	\$60.00	\$366,000.00	\$62.00	\$378,200.00	\$75.00	\$457,500.00	\$90.00	\$549,000.00
0079	4R01RSC	22	S.F.	Vertical Spall Repair	\$150.00	\$3,300.00	\$103.00	\$2,266.00	\$160.00	\$3,520.00	\$160.00	\$3,520.00
0080	4R00017	180	L.F.	Concrete Parapet Repair	\$350.00	\$63,000.00	\$400.00	\$72,000.00	\$500.00	\$90,000.00	\$350.00	\$63,000.00
0081	4R50EXR	400	L.F.	Epoxy Resin Injection	\$170.00	\$68,000.00	\$80.00	\$32,000.00	\$35.00	\$14,000.00	\$90.00	\$36,000.00
0082	4R51EXR	5	GAL	Furnish Epoxy Resin	\$500.00	\$2,500.00	\$210.00	\$1,050.00	\$130.00	\$650.00	\$53.00	\$265.00
0083	4ZH06SPP	3	Each	Furnish Steel Protection Plate, 10' x 6' x 1.50"	\$15,000.00	\$45,000.00	\$3,675.00	\$11,025.00	\$5,000.00	\$15,000.00	\$8,000.00	\$24,000.00
0084	4ZN01RO	380	S.Y.	Removal of Thin Overlay	\$50.00	\$19,000.00	\$42.00	\$15,960.00	\$120.00	\$45,600.00	\$100.00	\$38,000.00
0085	4ZN01TPO	380	S.Y.	Thin Polymer Overlay (Epoxy)	\$100.00	\$38,000.00	\$84.00	\$31,920.00	\$150.00	\$57,000.00	\$150.00	\$57,000.00
0086	5B01CSD	100	L.F.	Cleaning Existing Storm Drains	\$40.00	\$4,000.00	\$13.00	\$1,300.00	\$25.00	\$2,500.00	\$70.00	\$7,000.00
0087	5C10ND1	15	Each	Reconstructed Inlet, Type D1, Using New Grate and Frame	\$2,000.00	\$30,000.00	\$1,925.00	\$28,875.00	\$1,500.00	\$22,500.00	\$1,500.00	\$22,500.00
0088	5C10ND2	15	Each	Reconstructed Inlet, Type D2, Using New Grate and Frame	\$2,000.00	\$30,000.00	\$2,280.00	\$34,200.00	\$1,800.00	\$27,000.00	\$1,900.00	\$28,500.00
0089	5C10ND3	10	Each	Reconstructed Inlet, Type D3, Using New Grate and Frame	\$2,000.00	\$20,000.00	\$2,250.00	\$22,500.00	\$1,700.00	\$17,000.00	\$1,800.00	\$18,000.00
0090	5C40RSF	5	Each	Reset Frame	\$1,500.00	\$7,500.00	\$394.00	\$1,970.00	\$500.00	\$2,500.00	\$900.00	\$4,500.00
0091	5C40RPI	260	S.F.	Repair Inlets	\$100.00	\$26,000.00	\$89.00	\$23,140.00	\$100.00	\$26,000.00	\$100.00	\$26,000.00
0092	5C55CDS	3	Each	Cleaning Existing Drainage Structures	\$2,000.00	\$6,000.00	\$289.00	\$867.00	\$500.00	\$1,500.00	\$500.00	\$1,500.00
0093	5C60RIG	70	Each	Replace Existing Inlet Grate	\$800.00	\$56,000.00	\$367.00	\$25,690.00	\$750.00	\$52,500.00	\$400.00	\$28,000.00
0094	5E01ALC	100	L.F.	Asphalt Concrete Lip Curb	\$16.00	\$1,600.00	\$15.00	\$1,500.00	\$15.00	\$1,500.00	\$40.00	\$4,000.00
0095	5I01SNP	25	S.F.	Sign Panels	\$120.00	\$3,000.00	\$114.00	\$2,850.00	\$110.00	\$2,750.00	\$150.00	\$3,750.00
0096	5J01RBG	25	L.F.	Removal of Beam Guide Rail	\$25.00	\$625.00	\$6.00	\$150.00	\$20.00	\$500.00	\$20.00	\$500.00
0097	5J01RGR	25	L.F.	Raise Beam Guide Rail	\$160.00	\$4,000.00	\$155.00	\$3,875.00	\$150.00	\$3,750.00	\$45.00	\$1,125.00
0098	5J01RSG	25	L.F.	Reset Beam Guide Rail	\$280.00	\$7,000.00	\$285.00	\$7,125.00	\$275.00	\$6,875.00	\$45.00	\$1,125.00
0099	5J51BGE	25	L.F.	Beam Guide Rail Element	\$60.00	\$1,500.00	\$50.00	\$1,250.00	\$50.00	\$1,250.00	\$62.00	\$1,550.00
0100	5J54BGP	5	Each	Beam Guide Rail Post	\$210.00	\$1,050.00	\$205.00	\$1,025.00	\$300.00	\$1,500.00	\$225.00	\$1,125.00
0101	5J00004	5	Each	Beam Guide Rail Blockout	\$200.00	\$1,000.00	\$155.00	\$775.00	\$150.00	\$750.00	\$150.00	\$750.00
0102	5P10TMP	68000	L.F.	Temporary Pavement Striping	\$0.30	\$20,400.00	\$0.50	\$34,000.00	\$0.40	\$27,200.00	\$0.30	\$20,400.00
0103	5P11REM	1000	L.F.	Striping and Marking Removal, Mechanical	\$2.00	\$2,000.00	\$1.00	\$1,000.00	\$1.00	\$1,000.00	\$1.40	\$1,400.00
0104	5P12REM	68000	L.F.	Striping and Marking Removal, Hydromilling	\$0.60	\$40,800.00	\$1.00	\$68,000.00	\$0.90	\$61,200.00	\$0.60	\$40,800.00
0105	5P13TMP	77000	L.F.	Removable Black Line Mask, 8" Wide	\$2.40	\$184,800.00	\$3.00	\$231,000.00	\$1.00	\$77,000.00	\$2.50	\$192,500.00

Base Line Item Detail					D'annunzio & Sons, Inc.		Joseph M. Sanzari, Inc.		Gardner M. Bishop, Inc.		Railroad Construction Co., Inc.	
Item No.	Unit Code	QTY	UNIT	DESCRIPTION	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT	RATE	AMOUNT
0106	5P14TMP	39500	L.F.	Removable Wet Weather Pavement Marking Tape	\$2.00	\$79,000.00	\$2.50	\$98,750.00	\$2.50	\$98,750.00	\$2.00	\$79,000.00
0107	5P21LLS	31200	L.F.	Traffic Stripes, Long Life, Thermoplastic	\$1.00	\$31,200.00	\$0.80	\$24,960.00	\$0.80	\$24,960.00	\$0.90	\$28,080.00
0108	5P31LLM	1000	L.F.	Traffic Markings, Lines, Long Life, Thermoplastic	\$1.00	\$1,000.00	\$1.00	\$1,000.00	\$1.00	\$1,000.00	\$0.90	\$900.00
0109	5Q01FAL	1	L.S.	Furnish Field Office, Type A	\$50,000.00	\$50,000.00	\$63,000.00	\$63,000.00	\$60,000.00	\$60,000.00	\$120,000.00	\$120,000.00
0110	5Q02MFO	12	Mnth	Maintain Field Office	\$3,000.00	\$36,000.00	\$1,785.00	\$21,420.00	\$2,000.00	\$24,000.00	\$4,100.00	\$49,200.00
0111	5Q01RTC	1	L.S.	Repair Temporary Field Office Complex	\$60,000.00	\$60,000.00	\$61,950.00	\$61,950.00	\$55,000.00	\$55,000.00	\$60,000.00	\$60,000.00
0112	6A03RMS	150	L.F.	3" Rigid Metallic Conduit, on Structures	\$95.00	\$14,250.00	\$94.00	\$14,100.00	\$100.00	\$15,000.00	\$120.00	\$18,000.00
0113	6A02MLC	500	L.F.	#2 A.W.G. Multiple Lighting Cable	\$25.00	\$12,500.00	\$25.00	\$12,500.00	\$35.00	\$17,500.00	\$11.00	\$5,500.00
0114	6A06MLC	3700	L.F.	#6 A.W.G. Multiple Lighting Cable	\$7.00	\$25,900.00	\$13.00	\$48,100.00	\$5.00	\$18,500.00	\$9.00	\$33,300.00
0115	6A08GWR	2000	L.F.	#8 A.W.G. Ground Wire	\$5.00	\$10,000.00	\$4.00	\$8,000.00	\$4.50	\$9,000.00	\$5.00	\$10,000.00
0116	6A26JBR	15	Each	Junction Box Reconstruction	\$4,200.00	\$63,000.00	\$4,200.00	\$63,000.00	\$4,000.00	\$60,000.00	\$6,500.00	\$97,500.00
0117	6B03LST	1	Each	Lighting Standard, Type 3	\$5,500.00	\$5,500.00	\$5,100.00	\$5,100.00	\$5,000.00	\$5,000.00	\$7,500.00	\$7,500.00
0118	6B00002	1	Each	Luminaire, Type A, 150W HPS	\$1,500.00	\$1,500.00	\$1,300.00	\$1,300.00	\$1,300.00	\$1,300.00	\$1,200.00	\$1,200.00
0119	6JFACS0B	1	C.P.	Force Account for Calibration and Service (NO-BID)	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00
0120	6J1CS0B	2	Each	Calibration and Service (NO-BID)	\$6,700.00	\$13,400.00	\$6,700.00	\$13,400.00	\$6,700.00	\$13,400.00	\$6,700.00	\$13,400.00
0121	6JFAME0B	1	C.P.	Force Account for Maintenance of Electrical Work (NO-BID)	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00
0122	8A01MPT	1	L.S.	Furnishing Traffic Control Devices	\$20,000.00	\$20,000.00	\$200,000.00	\$200,000.00	\$50,000.00	\$50,000.00	\$50,000.00	\$50,000.00
0123	8A06MPT	10	Barr	Repair Temporary Impact Attenuators	\$400.00	\$4,000.00	\$50.00	\$500.00	\$400.00	\$4,000.00	\$350.00	\$3,500.00
0124	8A07MPT	2	Each	Repair Truck Mounted Impact Attenuators	\$2,000.00	\$4,000.00	\$1.00	\$2.00	\$1,000.00	\$2,000.00	\$1,000.00	\$2,000.00
0125	8CPTDOB	1	L.S.	Police Traffic Directors (NO-BID)	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00	\$15,000.00
0126	8A30MPT	5	Each	Furnishing Portable Variable Message Sign	\$5,000.00	\$25,000.00	\$4,000.00	\$20,000.00	\$1,000.00	\$5,000.00	\$5,500.00	\$27,500.00
0127	N8A0001	3000	L.F.	Furnishing Precast Concrete Construction Barrier	\$12.00	\$36,000.00	\$10.50	\$31,500.00	\$10.00	\$30,000.00	\$20.00	\$60,000.00
0128	N8A0002	8540	L.F.	Placing and Removing Precast Concrete Construction Barrier	\$20.00	\$170,800.00	\$22.00	\$187,880.00	\$25.00	\$213,500.00	\$50.00	\$427,000.00
0129	N8A0003	1700	L.F.	Resetting Precast Concrete Construction Barrier	\$5.00	\$8,500.00	\$14.70	\$24,990.00	\$25.00	\$42,500.00	\$7.00	\$11,900.00
0130	8B09MPT	1	L.S.	Picking Up and Returning Authority's Traffic Protection Devices	\$5,000.00	\$5,000.00	\$525.00	\$525.00	\$1,000.00	\$1,000.00	\$1,000.00	\$1,000.00
0131	8B15MPT	200	M.H.	Traffic Protection Patrol	\$100.00	\$20,000.00	\$100.00	\$20,000.00	\$60.00	\$12,000.00	\$60.00	\$12,000.00
0132	8B17MPT	6	Each	Furnishing Truck with Mounted Attenuator	\$2,000.00	\$12,000.00	\$4,000.00	\$24,000.00	\$1,000.00	\$6,000.00	\$6,000.00	\$36,000.00
0133	8B18MPT	10	Each	Furnishing Temporary Impact Attenuator	\$500.00	\$5,000.00	\$3,500.00	\$35,000.00	\$100.00	\$1,000.00	\$6,000.00	\$60,000.00
0134	8B19MPT	100	M.H.	Furnishing Truck with Mounted Attenuator for Engineer's Use	\$90.00	\$9,000.00	\$75.00	\$7,500.00	\$50.00	\$5,000.00	\$70.00	\$7,000.00
0135	8B20MPT	19	Each	Placing and Removing Temporary Impact Attenuator	\$2,000.00	\$38,000.00	\$2,500.00	\$47,500.00	\$100.00	\$1,900.00	\$2,000.00	\$38,000.00
0136	8B26MPT	350	Each	Installation, Maintenance, and Removal of Lane Closing	\$1,500.00	\$525,000.00	\$100.00	\$35,000.00	\$100.00	\$35,000.00	\$1,200.00	\$420,000.00
0137	8B34MPT	1500	L.F.	Modular Glare Screen System	\$20.00	\$30,000.00	\$17.00	\$25,500.00	\$20.00	\$30,000.00	\$17.00	\$25,500.00
0138	8DRRC0B	1	L.S.	Railroad Reimbursement Costs (NO-BID)	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00	\$30,000.00
0139	8C100SCL	1	L.S.	Maintenance and Protection of Traffic on State, County, and Local Roadways	\$45,000.00	\$45,000.00	\$26,000.00	\$26,000.00	\$60,000.00	\$60,000.00	\$60,000.00	\$60,000.00
0140	8C21MLR	1	L.S.	Maintenance and Protection of Traffic on Location No. 1	\$47,000.00	\$47,000.00	\$20,000.00	\$20,000.00	\$30,000.00	\$30,000.00	\$130,000.00	\$130,000.00
0141	6A00153	12	Each	Furnish Junction Box Cover Assembly	\$700.00	\$8,400.00	\$1,100.00	\$13,200.00	\$600.00	\$7,200.00	\$1,800.00	\$21,600.00
Base Total						\$11,707,000.00		\$11,746,478.00		\$11,827,920.00		\$14,935,891.00